

|  |   |
|--|---|
| Timestamp  | 15/06/2016 14:53                              |
| Time of Incident                                     | n/a   |
| Unit Name  | Tarbert 3                                     |
| Eirgrid Identifier                                   | TB3   |
| Location   | Kerry   |
| Market Area  | Ireland                                       |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 243   |
| Fuel   | HFO   |
| Anticipated # Hours until full availability restored | 9   |
| Forecast return to full availability                 | 23:59 15/06/2016                              |
| Reason   | Unit back midnight inclusive of start time    |
|  |   |
| Timestamp  | 09/06/2016 10:28                              |
| Time of Incident                                     | n/a   |
| Unit Name  | Tarbert 4                                     |
| Eirgrid Identifier                                   | TB4   |
| Location   | Kerry   |
| Market Area  | Ireland                                       |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 243   |
| Installed Capacity (MW)                              | 243   |
| Fuel   | HFO   |
| Anticipated # Hours until full availability restored | 8.5   |
| Forecast return to full availability                 | 19:00 09/06/2016                              |
| Reason   | Awaiting filter clean prior to re-declaration |
|  |   |
| Timestamp  | 31/05/2016 18:18                              |
| Time of Return to Service                            | 17:55   |
| Unit Name  | Great Island CCGT                             |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                       |
| Market Area  | Ireland                                       |
| Current Availability (MW)                            | 464   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | n/a   |
| Forecast return to full availability                 | n/a   |
| Reason   | Unit back available following trip.           |
|  |   |
| Time of email notification                           | 31/05/2016 15:32                              |
| Time of Incident                                     | 15:00 Tuesday 31/05/2016                      |
| Unit Name  | Great Island CCGT                             |
| Eirgrid Identifier                                   | GI4   |

|  |   |
|--|---|
| Location   | Wexford                                     |
| Market Area  | Ireland                                     |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Unknown, to be advised                               |   |
| Unknown  |   |
| Reason   | CCCW pumps trip due to low suction pressure |
|  |   |
| Time of email notification                           | 27/05/2016 13:56                            |
| Time of Incident                                     | 13:00 Friday 27/05/2016                     |
| Unit Name  | Great Island CCGT                           |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                     |
| Market Area  | Ireland                                     |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 64 hours from time of incident (estimated)  |
| Forecast return to full availability                 | 05:00 Monday 30/05/2016                     |
| Reason   | Gas Filter Blockage                         |
|  |   |
| Time of email notification                           | 26/05/2016 10:55                            |
| Time of Update                                       | 26/05/2016 10:55                            |
| Unit Name  | Great Island CCGT                           |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                     |
| Market Area  | Ireland                                     |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 24 hours from time of update (estimated)    |
| Forecast return to full availability                 | 11:00 Friday 27/05/2016                     |
| Reason   | Boiler tube leak                            |
|  |   |
| Time of email notification                           | 24/05/2016 23:02                            |
| Time of Incident                                     | 23:00 Tuesday 24/05/2016                    |
| Unit Name  | Great Island CCGT                           |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                     |
| Market Area  | Ireland                                     |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |

|  |   |
|--|---|
| Anticipated # Hours until full availability restored | 48 hours from time of incident (estimated)                                      |
| Forecast return to full availability                 | 23:00 Thursday 26/05/2016   |
| Reason   | Boiler tube leak  |
|  |   |
| Time of email notification                           | 23/05/2016 23:22  |
| Time of Incident                                     | 23:00 Monday 23/05/2016   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 24 hours from time of incident (estimated)                                      |
| Forecast return to full availability                 | 23:00 Tuesday 24/05/2016  |
| Reason   | Boiler tube leak  |
|  |   |
| Time of email notification                           | 21/05/2016 02:35  |
| Time of Incident                                     | 02:35 Saturday 21/05/2016   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 72 hours from time of incident (estimated)                                      |
| Forecast return to full availability                 | 02:35 Tuesday 24/05/2016  |
| Reason   | Boiler tube leak  |
|  |   |
| Time of email notification                           | 10/04/2016 00:10  |
| Time of Incident                                     | 23:28 Saturday 09/04/2016   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 48 hours from time of incident (estimated)                                      |
| Forecast return to full availability                 | 23:28 Monday 11/04/2016   |
| Reason   | Unit trip at 440 MW due to loss of both CW pumps on high differential pressure. |

|  |   |
|--|---|
| Time of email notification                           | 16/03/2016 06:00  |
| Time of Incident                                     | 06:00 Wednesday 16/03/2016                                |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 464   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 0 hours from time of incident (estimated)                 |
| Forecast return to full availability                 | 06:00 Wednesday 16/03/2016                                |
| Reason   | Unit Testing now complete. GI4 now fully available again. |
| Time of email notification                           | 13/03/2016 22:04  |
| Time of Incident                                     | 21:27 Sunday 13/03/2016                                   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 464   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 8 hours from time of incident (estimated)                 |
| Forecast return to full availability                 | 05:27 Monday 14/03/2016                                   |
| Reason   | Forced off due to testing and cable replacement.          |
| Timestamp  | 11/03/2016 13:39  |
| Time of Update                                       | 14:00   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 15  |
| Forecast return to full availability                 | Saturday 03:00  |
| Reason   | End of outage brought forward to meet Eirgrid request.    |
| Time of email notification                           | 09/03/2016 09:51  |
| Time of Outage Start                                 | 00:00 Saturday 05/03/2016                                 |

|  |   |
|--|---|
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 71 hours from now   |
| Forecast return to availability                      | 09:00 Saturday 12/03/2016 (previously 23:59 Thursday 10/03/2016 ) |
| Reason   | Scheduled Outage extension to start of testing programme          |
|  |   |
| Time of email notification                           | 02/03/2016 17:15  |
| Time of Outage                                       | 00:00 Saturday 05/03/2016   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 464   |
| Capacity Impacted (MW)                               | 464 – unit will be fully unavailable.                             |
| Installed Capacity (MW)                              | 464   |
| Fuel   | gas   |
| Anticipated # Hours until full availability restored | 144 hours   |
| Forecast return to full availability                 | 23:59 Thursday 10/03/2016   |
| Reason   | Scheduled Outage  |
|  |   |
| Timestamp  | 15/02/2016 13:26  |
| Time of Incident                                     | 12:49   |
| Unit Name  | Tarbert 4   |
| Eirgrid Identifier                                   | TB4   |
| Location   | Kerry   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 243   |
| Installed Capacity (MW)                              | 243   |
| Fuel   | HFO   |
| Anticipated # Hours until full availability restored | 49  |
| Forecast return to full availability                 | 13:49   |
| Reason   | Turbine HP oil pump failure                                       |
|  |   |
| Time of email notification                           | 28/01/2016 14:51  |
| Time of Incident                                     | 14:45 Thursday 28/01/2016   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |

|  |  |
|--|--|
| Market Area  | Ireland  |
| Current Availability (MW)                            | 464  |
| Capacity Impacted (MW)                               | 0  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | gas  |
| Anticipated # Hours until full availability restored | 0 hours from time of incident (estimated)                |
| Forecast return to full availability                 | 14:45 Thursday 28/01/2016                                |
| Reason   | Issue with water inlets now resolved unit back available |
|  |  |
| Time of email notification                           | 27/01/2016 16:55   |
| Time of Incident                                     | 15:40 Wednesday 27/01/2016                               |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 0  |
| Capacity Impacted (MW)                               | 464  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | gas  |
| Anticipated # Hours until full availability restored | 24 hours from time of incident (estimated)               |
| Forecast return to full availability                 | 15:40 Thursday 28/01/2016                                |
| Reason   | Debris in bandscreens                                    |
|  |  |
| Time of email notification                           | 22/01/2016 00:41   |
| Time of Incident                                     | 00:30 Friday 22/01/2016                                  |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 464  |
| Capacity Impacted (MW)                               | 0  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | gas  |
| Unknown, to be advised                               |  |
| Unknown  |  |
| Reason   | STMO work complete unit available                        |
|  |  |
| Time of email notification                           | 20/01/2016 23:17   |
| Time of Incident                                     | 23:00 Wednesday 20/01/2016                               |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 0  |
| Capacity Impacted (MW)                               | 465  |
| Installed Capacity (MW)                              | 465  |
| Fuel   | GAS  |

|  |  |
|--|--|
| Anticipated # Hours until full availability restored | 72 hours from time of incident (estimated)                 |
| Forecast return to full availability                 | 23:00 Saturday 23/01/2016                                  |
| Reason   | TCA Cooler outlet valve to HP Steam Drum emergency repair. |
|  |  |
| Time of email notification                           | 06/01/2016 00:57   |
| Time of Incident                                     | 21:00 Tuesday 05/01/2016                                   |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 400  |
| Capacity Impacted (MW)                               | 30   |
| Installed Capacity (MW)                              | 430  |
| Fuel   | distillate   |
| Unknown, to be advised                               |  |
| Unknown  |  |
| Reason   | Fuel Oil electric heater un-available                      |
|  |  |
| Time of email notification                           | 02/01/2016 19:33   |
| Time of Incident                                     | 19:30 Saturday 02/01/2016                                  |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 300  |
| Capacity Impacted (MW)                               | 164  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | Gas  |
| Unknown, to be advised                               |  |
| Unknown  |  |
| Reason   | Gas filter B delta p above 2.2 bar                         |
|  |  |
| Time of email notification                           | 02/01/2016 15:29   |
| Time of Incident                                     | 15:14 Saturday 02/01/2016                                  |
| Unit Name  | Great Island CCGT  |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 350  |
| Capacity Impacted (MW)                               | 114  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | Gas  |
| Anticipated # Hours until full availability restored | 72 hours from time of incident (estimated)                 |
| Forecast return to full availability                 | 15:14 Tuesday 05/01/2016                                   |
| Reason   | Main Gas Line B filter fouling                             |
|  |  |
| Time of email notification                           | 26/12/2015 00:12   |

|  |   |
|--|---|
| Time of Incident                                     | 23:48 Friday 25/12/2015                           |
| Unit Name  | Great Island CCGT                                 |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 12 hours from time of incident (estimated)        |
| Forecast return to full availability                 | 11:48 Saturday 26/12/2015                         |
| Reason   | Start timer following trip HP drum level control. |
|  |   |
| Timestamp  | 14/12/2015 08:56                                  |
| Time of Incident                                     | 06:00   |
| Unit Name  | Tarbert 4   |
| Eirgrid Identifier                                   | TB4   |
| Location   | Kerry   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 243   |
| Installed Capacity (MW)                              | 243   |
| Fuel   | HFO   |
| Anticipated # Hours until full availability restored | 60 Forecast return to full availability 18:00     |
| Reason   | Electrical fault on unit 380V board ...           |
|  |   |
| Timestamp  | 12/12/2015 08:00                                  |
| Time of Incident                                     | 08:00   |
| Unit Name  | Tarbert 3   |
| Eirgrid Identifier                                   | TB3   |
| Location   | Kerry   |
| Market Area  | Ireland   |
| Availability (MW)                                    | 0   |
| Capacity Impacted (MW)                               | 243   |
| Installed Capacity (MW)                              | 243   |
| Fuel   | HFO   |
| Anticipated # Hours until full availability restored | 11  |
| Forecast return to full availability                 | 12/12/15 19:00                                    |
| Reason   | Airheater wash                                    |
|  |   |
| Time of email notification                           | 11/12/2015 11:07                                  |
| Time of Incident                                     | 10:38 Friday 11/12/2015                           |
| Unit Name  | Great Island CCGT                                 |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |



|  |   |
|--|---|
| Capacity Impacted (MW)                               | 464                                       |
| Installed Capacity (MW)                              | 464                                       |
| Fuel   | Gas                                       |
| Anticipated # Hours until full availability restored | 2 hours from time of incident (estimated) |
| Forecast return to full availability                 | 12:38 Friday 11/12/2015                   |
| Reason   | Start timer following trip                |
|  |   |
| Time of email notification                           | 06/12/2015 09:16                          |
| Time of Incident                                     | 09:15 Sunday 06/12/2015                   |
| Unit Name  | Great Island CCGT                         |
| Eirgrid Identifier                                   | GI4                                       |
| Location   | Wexford                                   |
| Market Area  | Ireland                                   |
| Current Availability (MW)                            | 464                                       |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464                                       |
| Fuel   | Gas                                       |
| Anticipated # Hours until full availability restored | 0 hours from time of incident (estimated) |
| Forecast return to full availability                 | 09:15 Sunday 06/12/2015                   |
| Reason   | Unit 4 synchronised at 08:52              |
|  |   |
| Time of email notification                           | 29/11/2015 17:51                          |
| Time of Incident                                     | 17:47 Sunday 29/11/2015                   |
| Unit Name  | Great Island CCGT                         |
| Eirgrid Identifier                                   | GI4                                       |
| Location   | Wexford                                   |
| Market Area  | Ireland                                   |
| Current Availability (MW)                            | 464                                       |
| Capacity Impacted (MW)                               | 0   |
| Installed Capacity (MW)                              | 464                                       |
| Fuel   | Gas                                       |
| Anticipated # Hours until full availability restored | 0 hours from time of incident (estimated) |
| Forecast return to full availability                 | 17:47 Sunday 29/11/2015                   |
| Reason   | Synchronised on load at 17:47             |
|  |   |
| Time of email notification                           | 29/11/2015 15:53                          |
| Time of Incident                                     | 15:45 Sunday 29/11/2015                   |
| Unit Name  | Great Island CCGT                         |
| Eirgrid Identifier                                   | GI4                                       |
| Location   | Wexford                                   |
| Market Area  | Ireland                                   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464                                       |
| Installed Capacity (MW)                              | 464                                       |
| Fuel   | Gas                                       |
| Anticipated # Hours until full availability restored | 2 hours from time of incident (estimated) |

|  |  |
|--|--|
| Forecast return to full availability                 | 17:45 Sunday 29/11/2015                          |
| Reason   | Tripped on high HP drum level                    |
|  |  |
| Time of email notification                           | 29/11/2015 15:08                                 |
| Time of Return                                       | 14:00 Sunday 29/11/2015 approx                   |
| Unit Name  | Great Island CCGT                                |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 464  |
| Capacity Impacted (MW)                               | 0  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | Gas  |
| Anticipated # Hours until full availability restored | n/a Forecast return to full availability: n/a    |
| Reason   | Pipework inspection and maintenance complete ... |
|  |  |
| Time of email notification                           | 27/11/2015 12:38                                 |
| Time of update                                       | 12:37 Friday 27/11/2015                          |
| Unit Name  | Great Island CCGT                                |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 0  |
| Capacity Impacted (MW)                               | 464  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | Gas  |
| Anticipated # Hours until full availability restored | 45 hours from now                                |
| Forecast return to full availability                 | 10:00 Sunday 29/11/2015                          |
| Reason   | Pipework inspection and maintenance ...          |
|  |  |
| Time of email notification                           | 22/11/2015 08:                                   |
| 10 Time of Incident                                  | 08:10 Sunday 22/11/2015                          |
| Unit Name  | Great Island CCGT                                |
| Eirgrid Identifier                                   | GI4  |
| Location   | Wexford  |
| Market Area  | Ireland  |
| Current Availability (MW)                            | 0  |
| Capacity Impacted (MW)                               | 464  |
| Installed Capacity (MW)                              | 464  |
| Fuel   | Gas  |
| Anticipated # Hours until full availability restored | 148 hours from time of incident (estimated)      |
| Forecast return to full availability                 | 12:10 Saturday 28/11/2015                        |
| Reason   | Pipework inspection and maintenance ...          |
|  |  |
| Timestamp  | 20/11/2015 09:48                                 |
| Unit Name  | Great Island CCGT                                |
| Eirgrid Identifier                                   | GI4  |

|  |   |
|--|---|
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 240   |
| Forecast return to full availability                 | 06:00 Monday 30th November                                |
| Reason   | Continued inspection and maintenance of Fuel Gas line ... |
|  |   |
| Timestamp  | 19/11/2015 18:28  |
| Time of Incident                                     | 14:00   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | Unknown   |
| Forecast return to full availability                 | Unknown   |
| Reason   | Continued inspection and maintenance of Fuel Gas line ... |
|  |   |
| Time of email notification                           | 16/11/2015 14:39  |
| Time of Update                                       | 14:30 Monday 16/11/2015                                   |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 159 hours from time of update                             |
| Forecast return to full availability                 | 06:00 Monday 23/11/2015                                   |
| Reason   | Pipework inspection and maintenance ...                   |
|  |   |
| Time of email notification                           | 12/11/2015 17:02  |
| Time of update                                       | 17:00 Thursday 12/11/2015                                 |
| Unit Name  | Great Island CCGT   |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |

|  |   |
|--|---|
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 147 hours from time of update                   |
| Forecast return to full availability                 | 20:00 Wednesday 18/11/2015                      |
| Reason   | Pipework inspection                             |
|  |   |
| Time of email notification                           | 05/11/2015 08:05                                |
| Time of Incident                                     | 20:00 Wednesday 04/11/2015                      |
| Unit Name  | Great Island CCGT                               |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 24 hours from time of incident (estimated)      |
| Forecast return to full availability                 | 20:00 Thursday 05/11/2015                       |
| Reason   | Short term outage to repair gas inlet valve ... |
|  |   |
| Time of email notification                           | 04/11/2015 09:11                                |
| Time of Incident                                     | 09:00 Wednesday 04/11/2015                      |
| Unit Name  | Great Island CCGT                               |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 360   |
| Capacity Impacted (MW)                               | 104   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 36 hours from time of incident (estimated)      |
| Forecast return to full availability                 | 21:00 Thursday 05/11/2015                       |
| Reason   | Issue with gas inlet valve                      |
|  |   |
| Time of email notification                           | 03/11/2015 14:17                                |
| Time of Incident                                     | 12:00 Tuesday 03/11/2015                        |
| Unit Name  | Great Island CCGT                               |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford   |
| Market Area  | Ireland   |
| Current Availability (MW)                            | 400   |
| Capacity Impacted (MW)                               | 64  |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 72 hours from time of incident (estimated)      |

|  |   |
|--|---|
| Forecast return to full availability                 | 12:00 Friday 06/11/2015                       |
| Reason   | Issue with gas inlet valve                    |
|  |   |
| Time of email notification                           | 19/08/2015 08:37                              |
| Time of Incident                                     | 11:45 Sunday 16/08/2015                       |
| Unit Name  | Great Island CCGT                             |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                       |
| Market Area  | Ireland                                       |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 84 hours from time of incident (estimated)    |
| Forecast return to full availability                 | 23:59 Wednesday 19/08/2015                    |
| Reason   | Pump issue                                    |
|  |   |
| Timestamp  | 17/08/2015 09:12                              |
| Time of Incident                                     | 11:45   |
| Unit Name  | Great Island CCGT                             |
| Eirgrid Identifier                                   | GI4   |
| Location   | Wexford                                       |
| Market Area  | Ireland                                       |
| Current Availability (MW)                            | 0   |
| Capacity Impacted (MW)                               | 464   |
| Installed Capacity (MW)                              | 464   |
| Fuel   | Gas   |
| Anticipated # Hours until full availability restored | 72 Forecast return to full availability 11:45 |
| Reason   | Pump issue                                    |